







93 S Railroad Avenue Unit C Bergenfield NJ 07621 USA www.enapart.com sales@enapart.com



Via del Canneto 35. Borgosatollo, Brescia - Italia www.enapart.it vendite@enapart.it





Friedrich-Ebert-Anlage 36, 60325 Frankfurt am Main, Germany www.enapart.de anfrage@enapart.de



4 boulevard Carnot, 95400 villiers-le-bel, Paris, France www.enapart.fr sales@enapart.fr



〒584-0023 大阪府富田林市若松町 東2丁目2番16号 www.enapart.co.jp sales@enapart.co.jp



PLAZA NUESTRA SEÑORA DE LAS NIEVES 12 ,LOCAL ,50012,ZARAGOZA www.enapart.es ventas@enapart.es




PRIVADA 10 B SUR #3908 COL. ANZUREZ, C.P. 72530, PUEBLA, PUE www.enapart.com.mx sales@enapart.com.mx



MUNICIPIUL BUCUREŞTI, SECTOR 3, B-DUL BASARABIA, NR.250, CORP P+5 Hempstead, HP1 3AF , United Kingdom www.enapart.ro sales@enapart.ro



3 Austin Mews, High Street, Hemel www.enapart.co.uk sales@enapart.co.uk







Product	Description	
<u>11083000</u>	motor	
<u>110A3401</u>	Motor	
<u>110A3800</u>		
<u>D003303 "3052053"</u>	Motor	
<u>9/7 713314-5</u>		
C034400	motor	
<u>B004000</u>	Motor	
7133G01CD-5 736W		
<u>CO115.04</u>	Single-phase motor	
1U00700 {5726000088}		
P000101	motor	
B004302	Motor	
	Motor	
<u>C004007</u>	Motor	
AVS8		
NAV3		
CFCH50		
<u>11012311</u>	Motor	
<u>Type C036701</u>	motor	
11002712		
<u>C018603</u>		
11020201 "PB022843"	motor	
D009100 / 46SKAH4	replacement motor	
<u>11006221</u>	motor	
<u>C027801</u>	Motor	
<u>146-148 4013059</u>	Turbine	
<u>C001544</u>	motor	
<u>110827.01</u>	Electric motor	
<u>5726009961</u>		
<u>11021819</u>	Motor	
<u>11080500</u>		
11000214 "PB023831"	Motor	
<u>C047600 "481004900"</u>		
<u>11002703 / TRM.215</u>	ENGINE	
<u>11021806</u>	MOTOR	
E002600	motor	
<u>110A1100</u>		
<u>11U11011</u>		
<u>5726000667</u>	motor	
<u>D008200</u>		
Cod. CO115.04	Closed single-phase motor	
<u>11075200</u>	electric motor	
<u>CO087.00</u>	electric motor	
	· · · · · · · · · · · · · · · · · · ·	

**Enapart Group** 

! 3 Austin Mews, High Street, Hemel Hempstead, HP1 3AF, United Kingdom! RADWARD LTD United Kingdom





Product	Description
<u>11038023</u>	
C028700 "024B60125.006"	
<u>11027600</u>	motor
<u>11074900</u>	motor
<u>CO137.00</u>	
<u>11000216</u>	
<u>11006338</u>	single-phase motor
<u>11002704</u>	motor
<u>11U02731</u>	
<u>C029500</u>	ENGINES
D185/240 M9Z9 +GRG *6109HN*	
MOUNTING ARM KIT	MOUNTING ARM KIT
<u>11006321</u>	
<u>B012900</u>	motor
<u>D003501 "3052055"</u>	Motor
<u>11035100</u>	ENGINE
<u>11015300</u>	
<u>B008402</u>	
6M02H8 DDM 9/7 E6G3303 1F 6P 1V +SCT	ventilator
<u>C014300</u>	ENGINE
<u>RPM 110A0400</u>	motor
<u>W0F0206</u>	Motors
<u>W0F0221</u>	
<u>B016801</u>	
<u>31200600</u>	motor
<u>22321146</u>	
<u>11021403</u>	motor
RPM 11021403	Engine
<u>11000813</u>	motor
<u>11002730</u>	ENGINE
<u>B017101</u>	
<u>R000401</u>	motor
bearing cap for 11021814	bearing cap